

FORK-PACK

- DE

MONTAGEANWEISUNG
- GB

ASSEMBLY INSTRUCTIONS
- FR

INSTRUCTIONS DE MONTAGE
- IT

ISTRUZIONI DI MONTAGGIO
- NL

MONTAGE HANDLEIDING
- DK

MONTERINGSVEJLEDNING
- ES

INSTRUCCIONES DE MONTAJE
- SE

MONTERINGSANVISNING
- NO

MONTERINGSANVISNING
- FI

ASENNUSOHJEET
- PL

INSTRUKCJA MONTAZU
- JP

装着方法

INHALT:

CONTENTS:

CONTENU:

CONTENUTO:

INHOLD:

CONTENIDO:

INNEHÅLL:

INNHOUD:

SISÄLLYS:

ZAWARTOSC:

内容物

ORTLIEB


WATERPROOF

- M5 x 25



3x (A)
- 

2x (G)
- 

1x (H)
- 

1x (F)
- M4 x 14



2x (B)
- M4



2x (C)
- 

1x (D)
- 

2x (E)

!

1

Alu } ✓ = O.K.

Steel } ✓ = O.K.

Carbon } ✗

M5

✓ = O.K.

2

Alu } ✓ = O.K.

Steel } ✓ = O.K.

Carbon } ✗

M5

✓ = O.K.

3

Alu } ✓ = O.K.

Steel } ✓ = O.K.

Carbon } ✗

min. 150 mm

30 - 42 mm

✓ = O.K.

4

OPTION ACCESSORIES + = Art. # E240

ADAPTER 45° TO 30°

?

✗

✗

1

!

+3x (A)

+2x (G)

+1x (H)

UM KRATZER ZU VERMEIDEN, BENUTZE RAHMENSCHUTZFOLIE AN DEN KONTAKTSTELLEN (nicht beinhalten!). BENUTZE BEI CARBON-GABELN BITTE ZWINGEND DIE CARBON-SCHUTZINSERTS G UND H.

TO AVOID SCRATCHES, USE ADHESIVE FRAME PROTECTION AT CONTACT POINTS (not included). FOR CARBON FORKS, PLEASE BE SURE TO USE THE CARBON FIBER PROTECTIVE INSERTS G AND H.

+1x (A)

+1x (A)

+1x (A)

+1x (A)

+1x (G)

+1x (G)

+1x (G)

+1x (G)

+1x (H)

+1x (H)

+1x (H)

+1x (F)

2,5 Nm

M5 ✓ = O.K.

2

!

UM KRATZER ZU VERMEIDEN, BENUTZE RAHMENSCHUTZFOLIE AN DEN KONTAKTSTELLEN (nicht beinhalten!). BENUTZE BEI CARBON-GABELN BITTE ZWINGEND DAS CARBON-SCHUTZINSERT G.

TO AVOID SCRATCHES, USE ADHESIVE FRAME PROTECTION AT CONTACT POINTS (not included). FOR CARBON FORKS, PLEASE BE SURE TO USE THE CARBON FIBER PROTECTIVE INSERT G.

a)

M5

+1x (A)

+1x (G)

!

b)

+1x (B)

+1x (C)

+1x (D)

+1x (E)

+1x (F)

?

(->3.1 - 3.4)

a)

+1x (A)

+1x (G)

2,5 Nm

M5 ✓ = O.K.

b)

+1x (B)

2,5 Nm

M4 ✓ = O.K.

3

30 - 42 mm

✓ = O.K.

UM KRATZER ZU VERMEIDEN, BENUTZE RAHMENSCHUTZFOLIE AN DEN KONTAKTSTELLEN (nicht beinhalten!).

TO AVOID SCRATCHES, USE ADHESIVE FRAME PROTECTION AT CONTACT POINTS (not included)

+2x (B)

+2x (C)

+1x (D)

+2x (E)

+1x (F)

3.1

(D)

max. 3/4

1/4

30 - 42 mm

✓ = O.K.

1/2

(D)

1/2

3.2.

PRESS!

!

2x

3.3

1/2 (D)

(E)

1/2 (D)

(E)


30 - 42 mm

110 °C

230 °F

= 1 min.


3.4.




4. CLOSE




5. FIX




6. UNFIX



7.



8. ! CHECK FIXATION BEFORE EVERY RIDE!




9.

ACCESSORIES

! NO JUMP!



4 OPTION ACCESSORIES += Art. # E240 - ADAPTER 45° TO 30°



+= Art. # E235

